



Bug 2451106 (CVE-2026-33999) - CVE-2026-33999 xorg: xwayland: X.Org X server: Denial of Service via integer underflow in XKB compatibility map handling

Keywords: Security

Reported: 2026-03-25 06:29 UTC by OSIDB Bzimport

Status: NEW

Modified: 2026-04-29 13:07 UTC ([History](#))

Alias: CVE-2026-33999

CC List: 1 user ([show](#))

Product: Security Response

Fixed In Version:

Component: vulnerability

Clone Of:

Environment:

Version: unspecified

Last Closed:

Embargoed:

Hardware: All

OS: Linux

Priority: high

Severity: high

Target Milestone: ---

Assignee: Product Security DevOps Team

QA Contact:

Docs Contact:

URL:

Whiteboard:

Depends On:

Blocks:


TreeView+ [depends on](#) / [blocked](#)

Attachments	(Terms of Use)

Links

System	ID	Private	Priority	Status	Summary	Last Updated
Red Hat Product Errata	RHSA-2026:10739	0	None	None	None	2026-04-27 08:29:52 UTC
Red Hat Product Errata	RHSA-2026:11352	0	None	None	None	2026-04-28 11:21:02 UTC
Red Hat Product Errata	RHSA-2026:11369	0	None	None	None	2026-04-28 14:53:17 UTC

Red Hat Product Errata	RHSA-2026:11388	0	None	None	None	2026-04-28 17:58:05 UTC
Red Hat Product Errata	RHSA-2026:11656	0	None	None	None	2026-04-29 12:01:23 UTC
Red Hat Product Errata	RHSA-2026:11692	0	None	None	None	2026-04-29 13:07:52 UTC

OSIDB Bzimport  2026-03-25 06:29:42 UTC[Description](#)

Integer Underflow (Wraparound) vulnerability in the XKB compatibility map handling of the X.Org X server. The issue occurs in XkbSetCompatMap() when a previously truncated "compat" buffer leaves unused space that is later reused without correctly updating the count of valid entries. This can cause internal size/index calculations to become inconsistent and potentially underflow, resulting in a buffer read overrun when subsequent XKB requests are processed. An attacker with access to the X11 server (local or via remote X11 forwarding/SSH tunneling) can trigger the flaw without user interaction, leading to memory-safety violations and potentially a crash or more severe impact depending on how Xorg/Xwayland is deployed.

errata-xmlrpc 2026-04-27 08:29:51 UTC

[Comment 4](#)

This issue has been addressed in the following products:

Red Hat Enterprise Linux 9

Via [RHSA-2026:10739](#) <https://access.redhat.com/errata/RHSA-2026:10739>

errata-xmlrpc 2026-04-28 11:20:59 UTC

[Comment 5](#)

This issue has been addressed in the following products:

Red Hat Enterprise Linux 10

Via [RHSA-2026:11352](#) <https://access.redhat.com/errata/RHSA-2026:11352>

errata-xmlrpc 2026-04-28 14:53:16 UTC

[Comment 6](#)

This issue has been addressed in the following products:

Red Hat Enterprise Linux 9

Via RHSA-2026:11369 <https://access.redhat.com/errata/RHSA-2026:11369>

errata-xmlrpc 2026-04-28 17:58:04 UTC

[Comment 7](#)

This issue has been addressed in the following products:

Red Hat Enterprise Linux 9

Via RHSA-2026:11388 <https://access.redhat.com/errata/RHSA-2026:11388>

errata-xmlrpc 2026-04-29 12:01:21 UTC

[Comment 8](#)

This issue has been addressed in the following products:

Red Hat Enterprise Linux 8

Via RHSA-2026:11656 <https://access.redhat.com/errata/RHSA-2026:11656>

errata-xmlrpc 2026-04-29 13:07:51 UTC

[Comment 9](#)

This issue has been addressed in the following products:

Red Hat Enterprise Linux 8

Via RHSA-2026:11692 <https://access.redhat.com/errata/RHSA-2026:11692>

Note

You need to [log in](#) before you can comment on or make changes to this bug.

