



Home > Submit > 783323

# Submit #783323: Technostrobe HI-LED-WR120-G2 Obstruction Lighting Controller 5.5.0.1R6.03.30 Authentication Bypass Issues

**Title** Technostrobe HI-LED-WR120-G2 Obstruction Lighting Controller 5.5.0.1R6.03.30 Authentication Bypass Issues

**Description** Authentication enforcement is performed on the client side rather than the server. By intercepting and modifying HTTP responses, an attacker can bypass authentication.  
Bug 1.1 — Config Panel Bypass  
Target

http://technostrobe.shiky.demo:58746/Config/index\_config.html?id=1?userId=0002?keyId=NjIiNTAyZjNINA#StatusPage

### Steps to Reproduce

- Set up Burp Suite as HTTP proxy
  - Navigate to the config URL
  - In Burp's Intercept tab, intercept the POST response to /LoginCB then drop it
  - Modify the auth result to indicate success
  - Forward — the full configuration panel renders
- Bug 1.2 — Direct Access (No Proxy Needed)

GET /Technostrobe/surveillance\_generale.html?id=1?userId=0002?keyId=NjIiNTAyZjNINA

This one doesn't even need response manipulation. The server serves the page directly with no authentication check at all. Just visiting the URL works.

### Type URL in browser bar

Full surveillance dashboard loads

No login prompt. No session check. Nothing.

### Bug 1.3 — Light Control Board Bypass

Target

http://technostrobe.shiky.demo:58746/Technostrobe/surveillance\_ctfboard.html?id=1?userId=0001?keyId=NjIiNTAyZjNINA

This is the highest impact instance. The light control board allows:

Changing light flash patterns

## Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

## Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)

Toggle lights on/off  
Modifying timing sequences

WHAT THE LIGHT CONTROL BOARD CONTROLS

- Flash Pattern: -> can be changed remotely
- Flash Rate: [72 fpm] -> FAA requires specific rates
- Intensity: [100%] -> day/night levels
- Sync: [enabled] -> multi-tower sync

If this is tampered with:

- Lights go dark -> aviation hazard
- Wrong pattern -> confuses pilots
- Sync broken -> regulatory violation

Same bypass method as 1.1: intercept the /LoginCB response and modify it to indicate auth success.

The server does not validate session state for subsequent requests.

Root Cause:

Authentication decisions rely on client-side logic instead of server-side validation.

Impact

Full authentication bypass

Unauthorized access to admin functionality

No valid credentials required

Source  [https://github.com/shiky8/my-cve-vulnerability-research/blob/main/my\\_VulnDB\\_cves/CVE-TECHNOSTROBE-02-AuthBypass.md](https://github.com/shiky8/my-cve-vulnerability-research/blob/main/my_VulnDB_cves/CVE-TECHNOSTROBE-02-AuthBypass.md)

User  shiky8 (UID 96565)

Submission 03/20/2026 01:16 AM (17 days ago)

Moderation 04/04/2026 04:41 PM (16 days later)

Status Accepted

VulnDB entry  [Technostrobe HI-LED-WR120-G2 5.5.0.1R6.03.30 /LoginCB index\_config improper authentication]

Points 20