

- [Announcement](#)
- [Report Vulnerability](#)
- [Disclosure Policy](#)
- [Security Bulletin](#)
- [Acknowledgements](#)



The MediaTek Product Security Bulletin contains details of security vulnerabilities affecting certain MediaTek chipsets. Device OEMs have been notified of all the issues and the corresponding security patches for at least two months before publication. We take the security of our chipsets and our customers' products very seriously. At this time, we are not aware of any active exploitation of these vulnerabilities in the wild.

The severity of the identified vulnerabilities was conducted based on the Common Vulnerability Scoring System version 3.1 (CVSS v3.1).

Summary

Severity	CVEs
High	CVE-2026-20431, CVE-2026-20432, CVE-2026-20433



Details

CVE	CVE-2026-20431
Subcomponent	Modem
Severity	High
CWE	CWE-770 Allocation of Resources Without Limits or Throttling
Description	There is a possible system crash due to a logic error.
Affected Chipsets	MT6813, MT6815, MT6835, MT6878, MT6897, MT6899, MT6986, MT6991, MT6993, MT8668, MT8676, MT8678, MT8755, MT8775, MT8792, MT8793, MT8863, MT8873, MT8883
Report Source	Internal

CVE	CVE-2026-20432
Subcomponent	Modem
Severity	High
CWE	CWE-787 Out-of-bounds Write
Description	There is a possible out of bounds write due to a missing bounds check.



	MT6855, MT6873, MT6875, MT6877, MT6878, MT6879, MT6880, MT6883, MT6885, MT6886, MT6889, MT6890, MT6891, MT6893, MT6895, MT6896, MT6897, MT6899, MT6980, MT6983, MT6985, MT6989, MT6990, MT6991, MT6993, MT8668, MT8673, MT8675, MT8676, MT8678, MT8755, MT8771, MT8775, MT8781, MT8789, MT8791, MT8791T, MT8792, MT8793, MT8795T, MT8797, MT8798, MT8863, MT8873, MT8883, MT8893
Report Source	Internal

CVE	CVE-2026-20433
Subcomponent	Modem
Severity	High
CWE	CWE-787 Out-of-bounds Write
Description	There is a possible out of bounds write due to a missing bounds check.
Affected Chipsets	MT2735, MT2737, MT6813, MT6833, MT6833P, MT6835, MT6835T, MT6853, MT6853T, MT6855, MT6855T, MT6873, MT6875, MT6875T, MT6877, MT6877T, MT6877TT, MT6878, MT6878M, MT6879, MT6880, MT6883, MT6885, MT6886, MT6889, MT6890, MT6891, MT6893, MT6895, MT6895TT, MT6896, MT6897, MT6899, MT6980, MT6980D, MT6983, MT6983T, MT6985, MT6985T, MT6989, MT6989T, MT6990, MT6991, MT8668, MT8673, MT8675, MT8676, MT8678, MT8755, MT8771, MT8775, MT8791, MT8791T, MT8792, MT8793, MT8795T, MT8797, MT8798, MT8863, MT8873, MT8883, MT8893
Report Source	Internal



Subcomponent	sec boot
Severity	Medium
CWE	CWE-787 Out-of-bounds Write
Description	There is a possible out of bounds write due to an integer overflow.
Affected Chipsets	MT6813
Report Source	Internal

Versions

Version	Date	Description
1.0	April 7, 2026	Bulletin published.

Notes

Information above is generated only at the time of creation of this Security Bulletin. The list of affected chipsets could be not complete. For any further information, device OEMs can reach your MediaTek contact person if needed.

If you want to report a security vulnerability in MediaTek chipsets or products, please go to [Report Security Vulnerability](#) page on MediaTek website.

ABOUT MEDIATEK

NEWS



JOIN OUR NEWSLETTER

First Name *

Last Name *

Email Address *

SUBMIT

