



⋮ Documentation

🔍 Search document

May 2026 Security Bulletin

Published: 05/04/2026

This security bulletin is intended to help Qualcomm Technologies, Inc. (QTI) customers incorporate security updates in launched or upcoming devices. This document includes (i) a description of security issues that have been addressed in QTI’s proprietary code and (ii) links to publicly available code where security issues have been addressed.

Please reach out to securitybulletin@qti.qualcomm.com for any questions related to this bulletin.

Table of Contents

Announcements
Acknowledgements

This website processes personal data through our and third parties’ online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm’s [Cookie Policy](#). If you don’t want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on “Cookie Settings” below to update your preferences. You can also

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Cookie Settings

I Understand

We would like to thank these researchers for their contributions in reporting these issues to us.

CVE-2026-25254,CVE-2026-25255	Aaron Thacker (@thackeraaron)
CVE-2026-25262	Alexander Kozlov from Kaspersky ICS CERT
CVE-2026-25293	Tobias Scharnowski (@ScepticCtf), Felix Buchmann, and Krist
CVE-2025-47404	kmalloc1k (kmalloc1k)
CVE-2025-47405,CVE-2025-47406	heiheidada
CVE-2025-47407	Maher Azzouzi
CVE-2026-25266	Nicola Stauffer

Proprietary Software Issues

The tables below summarize security vulnerabilities that were addressed through proprietary software

This table lists high impact security vulnerabilities. Patches are being actively shared with OEMs, who have been notified and strongly recommended to deploy those patches on released devices as soon as possible. Please contact the device manufacturer for information on the patching status of released devices.

Public ID	Security Rating	CVSS Rating	Technology Area	Date Reported
			Qualcomm Software Center	01/09/2026
				03/14/2025
				02/19/2026
			AL	Internal
			firmware	Internal

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Technology Area	Date Reported
ST-POWER	Internal
Qualcomm Software Center	12/29/2025

This table lists moderate security vulnerabilities. OEMs have been notified and encouraged to patch these issues.

Public ID	Security Rating	CVSS Rating	Technology Area	Date Reported
CVE-2025-47405	Medium	High	Camera	06/01/2025
CVE-2025-47406	Medium	Medium	DSP Service	06/07/2025
CVE-2026-25266	Medium	Medium	Windows WLAN Host	12/22/2025

CVE-2026-25254

CVE ID	CVE-2026-25254
Title	Improper authorization in Qualcomm Software Center
Description	Improper authorization leads to Remote Code Execution via SocketIO inter
Technology Area	Qualcomm Software Center
Vulnerability Type	CWE-285: Improper Authorization
Access Vector	Remote
Security Rating	Critical
CVSS Rating	Critical
CVSS Score	9.8

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

/C:H/I:H/A:H

1.0

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Primary Bootloader

Description	memory corruption while processing a crafted ELF file in the Primary Boot
Technology Area	Boot
Vulnerability Type	CWE-123: Write-what-where Condition
Access Vector	Local
Security Rating	Critical
CVSS Rating	Medium
CVSS Score	6.9
CVSS String	CVSS:3.1/AV:P/AC:H/PR:L/UI:R/S:C/C:H/I:H/A:H
Date Reported	2025/03/14
Customer Notified Date	2026/04/20
Affected Chipsets*	MDM9x07, MDM9x45, MDM9x55, MDM9x65, MSM8909, MSM8916, MSM

CVE-2026-25293

CVE ID	CVE-2026-25293
Title	Incorrect authorization in PLC FW
Description	Buffer overflow due to incorrect authorization in PLC FW
Technology Area	PLC FW

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

/C:H/I:H/A:H

CVE-2025-47401

CVE ID	CVE-2025-47401
Title	Buffer Over-read in WLAN HAL
Description	Transient DOS when processing target power rate tables during channel c
Technology Area	WLAN HAL
Vulnerability Type	CWE-126 Buffer Over-read
Access Vector	Remote
Security Rating	High
CVSS Rating	Medium
CVSS Score	6.5
CVSS String	CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H
Date Reported	Internal
Customer Notified Date	2025/11/03
Affected Chipsets*	AR8035, Cologne, CQ7790, CQ8725S, CQ8750M, FastConnect 6200, Fast

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

malformed Fast Transition response fra

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

CVSS Rating	Medium
CVSS Score	6.5
CVSS String	CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H
Date Reported	Internal
Customer Notified Date	2025/11/03
Affected Chipsets*	AR8035, Cologne, CQ7790, CQ8725S, CQ8750M, CSR8811, FastConnect

CVE-2025-47408

CVE ID	CVE-2025-47408
Title	Untrusted Pointer Dereference in Power Optimization Firmware
Description	Memory corruption when another driver calls an IOCTL with invalid input/c
Technology Area	WINBLAST-POWER
Vulnerability Type	CWE-822 Untrusted Pointer Dereference
Access Vector	Local
Security Rating	High
CVSS Rating	High
CVSS Score	7.8

C:H/I:H/A:H

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

00, FastConnect 7800, IQX5121, IQX7

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Package Manager and Qualcomm Software
 to privilege escalation via gRPC server.

Technology Area	Qualcomm Software Center
Vulnerability Type	CWE-749: Exposed Dangerous Method or Function
Access Vector	Remote
Security Rating	High
CVSS Rating	High
CVSS Score	8.8
CVSS String	CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:C/C:H/I:H/A:H
Date Reported	2025/12/29
Customer Notified Date	2026/02/13
Affected Chipsets*	QSCv1.17.1, QSCv1.19.1, QSCv1.21.0, QPMv3.0.125.4, QPMv3.0.126.7, C

CVE-2025-47405

CVE ID	CVE-2025-47405
Title	Untrusted Pointer Dereference in Camera
Description	Memory corruption when processing camera sensor input/output control c
Technology Area	Camera
Vulnerability Type	CWE-822 Untrusted Pointer Dereference

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

C:H/I:H/A:H

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

00, IQX5121, IQX7181, QCA0000, SC8

CVE-2025-47406

CVE ID	CVE-2025-47406
Title	Buffer Over-read in DSP Service
Description	Information Disclosure while processing IOCTL handler callbacks without
Technology Area	DSP Service
Vulnerability Type	CWE-126 Buffer Over-read
Access Vector	Local
Security Rating	Medium
CVSS Rating	Medium
CVSS Score	6.1
CVSS String	CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:N/A:L
Date Reported	2025/06/07
Customer Notified Date	2025/11/03
Affected Chipsets*	Cologne, FastConnect 6700, FastConnect 6900, FastConnect 7800, IQX51

CVE-2026-25266

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

dows host

g IOCTL command when device is in p

hod or Function

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

CVSS String	CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:N/I:N/A:H
Date Reported	2025/12/22
Customer Notified Date	2026/04/06
Affected Chipsets*	Cologne, FastConnect 6900, FastConnect 7800, SC8380XP, Snapdragon A

*The list of affected chipsets may not be complete. For latest information, device OEMs can contact QTI directly at www.qualcomm.com/support.

Open Source Software Issues

The tables below summarize security vulnerabilities that were addressed through open source software

This table lists high impact security vulnerabilities. Patches are being actively shared with OEMs, who have been notified and strongly recommended to deploy those patches on released devices as soon as possible. Please contact the device manufacturer for information on the patching status of released devices.

Public ID	Security Rating	CVSS Rating	Technology Area	Date Reported
CVE-2026-24082	High	High	Automotive GPU	Internal

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

ve been notified and encouraged

Technology Area	Date Reported
ive Audio	06/07/2025
vice	06/27/2025

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Description	memory corruption when copying data from a freed source while executin
Technology Area	Automotive GPU
Vulnerability Type	CWE-416 Use After Free
Access Vector	Local
Security Rating	High
CVSS Rating	High
CVSS Score	7.8
CVSS String	CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H
Date Reported	Internal
Customer Notified Date	2026/02/02
Affected Chipsets*	AR8031, AR8035, CSRA6620, CSRA6640, FastConnect 6200, FastConnect
Patch**	<ul style="list-style-type: none"> https://git.codelinaro.org/clo/la/kernel/msm-5.15/-/commit/e778bf9541f

CVE-2025-47404

CVE ID	CVE-2025-47404
Title	Buffer Copy Without Checking Size of Input in Automotive Audio
Description	Memory corruption when dynamically changing the size of a previously all

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

...king Size of Input ('Classic Buffer Over

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

C:H/I:H/A:L

Customer Notified Date	2025/11/03
Affected Chipsets*	5G Fixed Wireless Access Platform, AR8031, AR8035, C-V2X 9150, CSRA6
Patch**	<ul style="list-style-type: none"> https://git.codelinaro.org/clo/la/platform/vendor/opensource/audio-kern

CVE-2025-47407

CVE ID	CVE-2025-47407
Title	Time-of-check Time-of-use (TOCTOU) Race Condition in DSP Service
Description	Memory corruption while creating a process on the digital signal process
Technology Area	DSP Service
Vulnerability Type	CWE-367 Time-of-check Time-of-use (TOCTOU) Race Condition
Access Vector	Local
Security Rating	Medium
CVSS Rating	High
CVSS Score	7.8
CVSS String	CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H
Date Reported	2025/06/27
Customer Notified Date	2025/11/03

200, FastConnect 6700, FastConnect 6

[platform/vendor/qcom/opensource/dsp-](#)

test information, device OEMs can

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Security ratings of issues included in Android security bulletins and these bulletins match in the most common scenarios but may differ in some cases due to one of the following reasons:

- Consideration of security protections such as SELinux not enforced on some platforms
- Differences in assessment of some specific scenarios that involves local denial of service or privilege escalation vulnerabilities in the high level OS kernel

All Qualcomm products mentioned herein are products of Qualcomm Technologies, Inc. and/or its subsidiaries.

Qualcomm is a trademark of Qualcomm Incorporated, registered in the United States and other countries. Other product and brand names may be trademarks or registered trademarks of their respective owners.

This technical data may be subject to U.S. and international export, re-export, or transfer ("export") laws. Diversion contrary to U.S. and international law is strictly prohibited.

Qualcomm Technologies, Inc.
San Diego, CA 92121
U.S.A.

© 2022 Qualcomm Technologies, Inc. and/or its subsidiaries. All rights reserved.

Light Dark **Auto**

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also

update your cookie preferences at any time by clicking the [Do Not Sell or Share My Personal Information](#) link at the bottom of this website.

Quick links

Company info

Stay connected

Get the latest Qualcomm and industry information delivered to your inbox.

 [Subscribe](#)

[Manage your subscription](#)

[Cookie Settings](#)

: [English \(US\)](#)

This website processes personal data through our and third parties' online tracking technologies, including analytics and advertising cookies. To learn more about how we and our affiliates within the Qualcomm Group may use your personal data and cookies, please review the Privacy Policy published at the bottom of this website and Qualcomm's [Cookie Policy](#). If you don't want to share your website activities, including browsing behavior, with our third-party partners via these tracking technologies, click on "Cookie Settings" below to update your preferences. You can also