



Home > Submit > 785538

Submit #785538: Belkin F9K1015 1.00.10 Stack-based Buffer Overflow

Title Belkin F9K1015 1.00.10 Stack-based Buffer Overflow

Description A vulnerability identified as critical has been detected in Belkin F9K1015 1.00.10. This impacts the function formCrossBandSwitch of the file /goform/formCrossBandSwitch of the component webs. Performing a manipulation of the argument webpage results in stack-based overflow. As a result, by requesting the page, an attacker can easily execute a denial of service attack or remote code execution.

Source https://github.com/Litengzheng/vuldb_new/blob/main/Belkin%20F9K1015/vul_5/README.md

User LtzHust (UID 95660)

Submission 03/22/2026 11:25 AM (15 days ago)

Moderation 04/05/2026 05:30 PM (14 days later)

Status Accepted

VulDB entry 355402 [Belkin F9K1015 1.00.10 formCrossBandSwitch webpage stack-based overflow]

Points 20

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)