



Home > Submit > 792865

Submit #792865: Tenda F451_kfw_V1.0.0.7_cn_svn7958 V1.0.0.7 Buffer Overflow

Title Tenda F451_kfw_V1.0.0.7_cn_svn7958 V1.0.0.7 Buffer Overflow

Description We found an overflow vulnerability in httpd :
 In WrlclientSet function,it reads in a user-provided parameter GO.
 And the variable s_1 will be passed to the sub_3A494 function without any length check, which may overflow the stack-based buffer s_ by sprintf.
 As a result, by requesting the page, an attacker can easily execute a denial of service attack or remote code execution.

Source <https://github.com/Jimi-Lab/cve/issues/12>

User Jimi (UID 68862)

Submission 03/30/2026 03:29 PM (13 days ago)

Moderation 04/11/2026 06:03 PM (12 days later)

Status Moderated

VulDB entry [\[Tenda F-451 1.0.0.7 httpd /goform/WrlclientSet GO stack-based overflow\]](#)

Points 20

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)