



Home > Submit > 792876

Submit #792876: Tenda F451_kfw_V1.0.0.7_cn_svn7958 V1.0.0.7 Buffer Overflow

Title Tenda F451_kfw_V1.0.0.7_cn_svn7958 V1.0.0.7 Buffer Overflow

Description We found an overflow vulnerability in httpd :
 In fromqossetting function,it reads in a user-provided parameter qos,

 And the variable src is passed to the strcpy function without any length check, which may overflow the stack-based buffer dest.

 As a result, by requesting the page, an attacker can easily execute a denial of service attack or remote code execution.

Source <https://github.com/Jimi-Lab/cve/issues/18>

User Jxm666 (UID 96919)

Submission 03/30/2026 04:03 PM (13 days ago)

Moderation 04/12/2026 09:22 AM (13 days later)

Status Accepted

VulDB entry 356998 [Tenda F451 1.0.0.7_cn_svn7958 /goform/qossetting fromqossetting qos stack-based overflow]

Points 19

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)