



Home > Submit > 792877

# Submit #792877: Tenda F451\_kfw\_V1.0.0.7\_cn\_svn7958 V1.0.0.7 Buffer Overflow

**Title** Tenda F451\_kfw\_V1.0.0.7\_cn\_svn7958 V1.0.0.7 Buffer Overflow

**Description** We found an overflow vulnerability in http://  
 in fromSetipBind function, it reads in a user-provided parameter page.  
 And the variable v8 is passed to the sprintf function without any length check, which may overflow the stack-based buffer s.  
 As a result, by requesting the page, an attacker can easily execute a denial of service attack or remote code execution.

**Source** <https://github.com/Jimi-Lab/cve/issues/19>

**User** jxm666 (UID 66910)

**Submission** 03/30/2026 04:04 PM (13 days ago)

**Moderation** 04/12/2026 09:22 AM (13 days later)

**Status** Verified

**VulDB entry** [\[Tenda F451\\_1.0.0.7\\_cn\\_svn7958 /golorm/SetipBind fromSetipBind page stack-based overflow\]](#)

**Points** 19

## Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

## Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)