



Home > Submit > 768983

Submit #768983: Tenda i3 V1.0.0.6(2204) Buffer Overflow

Title	Tenda i3 V1.0.0.6(2204) Buffer Overflow
Description	<p>Affected component(s): httpd, formexeCommand, /goform/exeCommand, cmdinput</p> <p>Attack vector(s): Remote exploitation via crafted HTTP POST to /goform/exeCommand with an overly long cmdinput.</p> <p>Suggested description: Tenda i3 V1.0.0.6(2204) contains a stack-based buffer overflow in httpd due to insufficient length validation of the cmdinput parameter in formexeCommand. A remote attacker can send a crafted request to /goform/exeCommand to trigger a denial of service or potentially achieve code execution.</p> <p>Discoverer(s)/Credits: Svigo, Huazhong University of Science and Technology</p>
Source	https://github.com/Svigo-o/Tenda_vul/tree/main/tenda-i3-formexeCommand-cmdinput-buffer-overflow
User	Svigo (UID 95904)
Submission	02/27/2026 09:18 AM (1 month ago)
Moderation	03/08/2026 01:39 PM (9 days later)
Status	Verified
VulDB entry	CVE-2026-2204 [Tenda i3 1.0.0.6(2204) /goform/exeCommand formexeCommand cmdinput stack-based overflow]
Points	20

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)