



Home > Submit > 769019

Submit #769019: Tenda FH1202 V1.2.0.14(408) Buffer Overflow

Title Tenda FH1202 V1.2.0.14(408) Buffer Overflow

Description Stack-based buffer overflow in httpd: /goform/AdvSetWrlsafeset calls formWrlsafeset, which copies the mit_ssid parameter into a fixed-size stack buffer using sprintf without bounds checking. A long mit_ssid overflows the stack, causing a crash (DoS) and potentially enabling control-flow hijack in constrained environments.

Source https://github.com/Svigo-0/Tenda_vul/tree/main/tenda-fh1202-advsetwrlsafeset-mit-ssid-buffer-overflow

User Fm95 (UID: 95969)

Submission 02/27/2026 10:13 AM (1 month ago)

Moderation 03/08/2026 05:23 PM (9 days later)

Status PENDING

VulDB entry [\[Tenda FH1202 1.2.0.14\(408\) /goform/AdvSetWrlsafeset formWrlsafeset mit_ssid/mit_ssid_index stack-based overflow\]](#)

Points 19

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)