

[Home](#) > [Submit](#) > 769020 

# Submit #769020: Tenda FH1202 V1.2.0.14(408) Buffer Overflow

<b>Title</b>	Tenda FH1202 V1.2.0.14(408) Buffer Overflow
<b>Description</b>	Stack-based buffer overflow in <code>httpd: /goform/AdvSetWrIsafeset</code> calls <code>formWrIsafeset</code> , which writes the <code>mit_ssid_index</code> parameter into a fixed-size stack buffer via <code>sprintf</code> without length validation. An oversized <code>mit_ssid_index</code> triggers a stack overflow leading to DoS and possible RCE.
<b>Source</b>	<a href="https://github.com/Svigo-o/Tenda_vul/tree/main/tenda-fh1202-advsetwrIsafeset-mit-ssid-index-buffer-overflow">https://github.com/Svigo-o/Tenda_vul/tree/main/tenda-fh1202-advsetwrIsafeset-mit-ssid-index-buffer-overflow</a>
<b>User</b>	Fan95 (UID 95969)
<b>Submission</b>	02/27/2026 10:14 AM (1 month ago)
<b>Moderation</b>	03/08/2026 05:23 PM (9 days later)
<b>Status</b>	<span>Duplicate</span>
<b>VulDB entry</b>	<a href="#">349773</a> [Tenda FH1202 1.2.0.14(408) /goform/AdvSetWrIsafeset formWrIsafeset mit_ssid/mit_ssid_index stack-based overflow]
<b>Points</b>	0

## Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

## Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)