



Home > Submit > 769039

Submit #769039: Tenda FH1202 V1.2.0.14(408) Buffer Overflow

Title	Tenda FH1202 V1.2.0.14(408) Buffer Overflow
Description	Stack-based buffer overflow in httpd: /goform/NatStaticSetting invokes fromNatStaticSetting, which writes the page parameter into a fixed-size stack buffer using sprintf without bounds validation. A long page causes stack overflow, resulting in DoS and potential code execution.
Source	https://github.com/Svigo-o/Tenda_vul/tree/main/tenda-fh1202-natstaticsetting-page-buffer-overflow
User	m202572177 (UID: 95972)
Submission	02/27/2026 10:26 AM (1 month ago)
Moderation	03/08/2026 05:23 PM (9 days later)
Status	Solved
VulDB entry	VulDB Entry [Tenda FH1202 1.2.0.14(408) /goform/NatStaticSetting fromNatStaticSetting page stack-based overflow]
Points	18

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)