



Home > Submit > 769040

Submit #769040: Tenda FH1202 V1.2.0.14(408) Buffer Overflow

Title Tenda FH1202 V1.2.0.14(408) Buffer Overflow

Description Stack-based buffer overflow in httpd: /goform/DhcpListClient invokes fromDhcpListClient, which copies the page parameter into a fixed-size stack buffer (e.g., s_2) using sprintf with no bounds check. A long page value overflows the stack, causing DoS and possibly RCE.

Source https://github.com/Svigo-o/Tenda_vul/tree/main/tenda-fh1202-dhcpclient-page-buffer-overflow

User m202572177 (UID 95972)

Submission 02/27/2026 10:26 AM (1 month ago)

Moderation 03/08/2026 05:23 PM (9 days later)

Status Accepted

VulDB entry 349776 [Tenda FH1202 1.2.0.14(408) /goform/DhcpListClient fromDhcpListClient page stack-based overflow]

Points 18

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)