



Home > Submit > 769173

Submit #769173: Tenda W3 V1.0.0.3(2204) Buffer Overflow

Title	Tenda W3 V1.0.0.3(2204) Buffer Overflow
Description	A stack-based buffer overflow exists in Tenda w3 v1.0.0.3(2204) in formSetAutoPing at the /goform/setAutoPing endpoint. The handler copies the ping1 POST parameter into a fixed-size stack buffer without validating length. A crafted request with an excessively long ping1 value causes stack corruption, leading to a crash and possible code execution. The vulnerable flow is reached when linkEn=1 and ping1 is processed.
Source	https://github.com/Svigo-0/Tenda_vul/tree/main/tenda-w3-setautoping-ping1-buffer-overflow
User	Svigo_0 (UID 95970)
Submission	02/27/2026 03:06 PM (1 month ago)
Moderation	03/11/2026 03:01 PM (12 days later)
Status	Accepted
VulDB entry	VUL-2026-0000 [Tenda W3 1.0.0.3(2204) POST Parameter /goform/setAutoPing formSetAutoPing ping1/ping2 stack-based overflow]
Points	20

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)