



Home > Submit > 769177

Submit #769177: Tenda W3 V1.0.0.3(2204) Buffer Overflow

Title	Tenda W3 V1.0.0.3(2204) Buffer Overflow
Description	A stack-based buffer overflow exists in Tenda w3 V1.0.0.3(2204) in the HTTP handler formexeCommand exposed at /goform/exeCommand. The POST parameter cmdinput is copied into a fixed-length stack buffer without length validation. An overly long cmdinput value overwrites the stack, resulting in a crash and potential code execution within the httpd process.
Source	https://github.com/Svigo-0/Tenda_vul/tree/main/tenda-w3-formexeCommand-cmdinput-buffer-overflow
User	Svigo_0 (UID 95976)
Submission	02/27/2026 03:08 PM (1 month ago)
Moderation	03/11/2026 03:02 PM (12 days later)
Status	Verified
VulDB entry	[Tenda W3 1.0.0.3(2204) HTTP /goform/exeCommand formexeCommand cmdinput stack-based overflow]
Points	10

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)