

Download for Tapo C100 V5

Please choose hardware version:

V5 ▾

> [How to Find the Hardware Version on Your TP-Link Device](#)

IMPORTANT: Model and hardware version availability varies by region. Please refer to your TP-Link regional website to determine product availability.

Vx.0=Vx.6/Vx.8/Vx.9(eg:V1.0=V1.6/V1.8/V1.9)

Vx.x0=Vx.x6/Vx.x8/Vx.x9 (eg:V1.20=V1.26/V1.28/V1.29)

Vx.x0=Vx.x2/Vx.x3 (eg:V3.30=V3.32/V3.33)

Pro

Tapo

Ma

Tapo

Tapo

Tapo

Tapo

[Tapo Camera_Quick Installation Guide\(EU1_12 Languages\)](#) ↓

[Tapo Camera_Quick Installation Guide\(29 Languages\)](#) ↓

From Germany?

Get products, events and services for your region.

GO

Other Option

Setup Video

FAQ

Firmware Release Note

Apps

GPL Code

Firmware Release Note

Refer the FAQ to update firmware.

Tapo C100(EU)_V5_1.4.4 Build 260303

Published Date: 2026-03-31

Modifications and Bug Fixes:
Enhanced device stability and security.

Tapo C100(EU)_V5_1.3.5 Build 251109

Published Date: 2025-11-13

Modifications and Bug Fixes:
1. Fixed the issue where the camera may fail to detect the router Wi-Fi during reconfiguration via the iOS app after a reset.
2. Enhanced device performance.

Tapo C100(EU)_V5_1.3.4 Build 250911

From Germany?

Get products, events and services for your region.

GO

Other Option

Modifications and Bug Fixes:
1. Added support for 12-hour Time option and more timestamp formats.
2. Optimized the SD card recording performance.
3. Improved device performance and stability.
4. Fixed some minor bugs.

Tapo C100(EU)_V5_1.0.11 Build 240617

Published Date: 2024-07-10

Modifications and Bug Fixes:
1. Optimized the performance of configuration and recording.
2. Enhanced device stability.
3. Fixed some minor bugs.

Tapo C100(EU)_V5_1.0.10 Build 240527

Published Date: 2024-06-25

Modifications and Bug Fixes:

- 1. Removed the 1fps and 10fps options from the Frame Rate.
- 2. Optimized device performance and stability.
- 3. Fixed some minor bugs.

Tapo C100(EU)_V5_1.0.5 Build 240306

Published Date: 2024-04-07

Modifications and Bug Fixes:

- 1. Improved live view performance.
- 2. Fixed some minor bugs.

From Germany?

Get products, events and services for your region.

GO

Other Option

About Us

News

Technology Library

Corporate Information

Blog

Our Security Commitment

Awards

Sustainability

Security Advisory

Privacy Policy

Ethical Violation Complaint

Accessibility

Contact Us



©2026 TP-Link Systems Inc. and its affiliated companies. All rights reserved.

Worldwide / English

TP-Link, Tapo, Kasa, Omada, VIGI, Aginet, HomeShield, and Tapo Care branded products are products of TP-Link Systems Inc. or its affiliates.

Note: Some services and materials may require you to accept additional terms and conditions before access or use.

References to "TP-Link" may include TP-Link Systems Inc., its subsidiaries, or business units within the TP-Link corporate structure, as applicable.

The materials provided, including but not limited to press releases, presentations, blog posts, and webcasts, are current as of the date of publication and may be superseded by subsequent updates.

From Germany?

Get products, events and services for your region.

GO

Other Option