

Select your country or region to find out what content fits your location

Remember for next time?

Global / English

Continue



SAMSUNG

Products

Support

Technologies

Foundry

News & Events

Sustainability

About Us



Product Security Update

Search Keyword

Filters

Reset



Filter

ge leads to a Denial of Service

2026



2025



2024



2023



buffer overflow

2022



Cookies



This site uses cookies to personalise your experience, analyse site traffic. By Clicking Accept or continuing to browse the site you are agreeing to our use of cookies.

You can read our [Privacy Policy](#) and [Cookie Policy](#) for more information.

Configure

Accept all

High

CVE-2025-52909

Incorrect Handling of NL80211 vendor command leads to a buffer overflow

2026-04-06

[Learn more >](#)

Medium

CVE-2025-54324

Incorrect Handling of DL NAS Transport packet leads to a Denial of Service

2026-04-06

[Learn more >](#)

Medium

CVE-2025-54328

Stack-based Buffer Overflow occurred while parsing SMS RP-DATA messages

2026-04-06

[Learn more >](#)

High

CVE-2025-54601

Improper synchronization on a global variable leads to a double free vulnerability

2026-04-06

[Learn more >](#)

High

CVE-2025-54602

Improper synchronization on a global variable leads to a use after free vulnerability

2026-04-06

[Learn more >](#)

Cookies

This site uses cookies to personalise your experience, analyse site traffic. By Clicking Accept or continuing to browse the site you are agreeing to our use of cookies.

You can read our [Privacy Policy](#) and [Cookie Policy](#) for more information.

Medium

CVE-2025-57834

The absence of proper input validation leads to a Denial of Service

2026-04-06

[Learn more >](#)

Medium

CVE-2025-57835

Improper memory initialization results in an illegal memory access, causing a system crash.

2026-04-06

[Learn more >](#)

Medium

CVE-2025-58349

Incorrect handling of LTE MAC packets containing many MAC Control Elements (CEs) leads to baseband crashes.

2026-04-06

[Learn more >](#)

[View more](#)

[Home](#) > [Support](#) > [Product Security Update](#)

Products	Support	Technologies	News & Events	About Us
Products Type DRAM SSD eStorage CXL Memory MCP Processor Image Sensor Display IC Security Solution Power IC LED ↗	Quality Support Quality Management Customer Service Regulatory Information Product Security Update Tools & Resources Technical Resources Fabrication Process Dictionary	Collaboration Hub DS Open-Ecosystem Contact Info Global Network B2B Workplace ↗ SOC-Developer ↗	On-device AI Mobile PKG GPU Technology ENSS Pixel Technology Ultra-High Resolution HDR Technology Remosaic Technology	Company Info

Cookies

This site uses cookies to personalise your experience, analyse site traffic. By Clicking Accept or continuing to browse the site you are agreeing to our use of cookies. You can read our [Privacy Policy](#) and [Cookie Policy](#) for more information.

[Display ↗](#)

Applications

- AI
- Server
- Automotive
- Network
- Mobile
- Lifestyle

Consumer Storage Support

- Overview
- Tools & Software
- Documents
- FAQs
- Warranty
- Magician Software
- SSD Upgrade

Foundry

- About Samsung Foundry
- Process Technology
- Advanced Packaging
- SAFE™
- Foundry Events
- Manufacturing
- Application Specific Service
- Tech Archives
- US Fab
- CONNECT ↗

Sustainability

- Highlights
- Environment
- Labor & Human Rights
- Corporate Citizenship
- Sustainable Supply Chain

LOCATIONS

Careers

[Search Jobs](#)



Global / English

[Privacy](#) [Legal](#) [Cookies](#)

[Accessibility](#) [Imprint\(EU\)](#)

[SSI Sales T&C\(US\)](#)

[Job Applicant Privacy Policy\(US\)](#) [Sitemap](#)

Stay in the loop?



Semiconductor Newsroom  

Cookies

This site uses cookies to personalise your experience, analyse site traffic. By Clicking Accept or continuing to browse the site you are agreeing to our use of cookies.

You can read our [Privacy Policy](#) and [Cookie Policy](#) for more information.