



Home > Submit > 759626

Submit #759626: Tenda F453 v1.0.0.3 Buffer Access Using Size of Source Buffer

Title Tenda F453 v1.0.0.3 Buffer Access Using Size of Source Buffer

Description A vulnerability was found in Tenda F453 v1.0.0.3. It has been declared as critical. Affected by this vulnerability is the function fromSetIpBind of the file /goform/SetIpBind of the component httpd. The manipulation of the argument page with an unknown input leads to a buffer overflow vulnerability.

Source https://github.com/Litengzheng/vul_db/blob/main/F453/vul_79/README.md

User LizHue2 (UID: 95662)

Submission 02/17/2026 03:58 PM (2 months ago)

Moderation 02/28/2026 07:55 AM (11 days later)

Status Reviewed

VulDB entry [VUL-2026-00000](#) [Tenda F453 1.0.0.3 /goform/SetIpBind fromSetIpBind page buffer overflow]

Points 18

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)