

[Home](#) > [Submit](#) > 765329

Submit #765329: Tenda FH451 V1.0.0.9 Stack-based Buffer Overflow

Title Tenda FH451 V1.0.0.9 Stack-based Buffer Overflow

Description A vulnerability was found in Tenda FH451 V1.0.0.9. Affected by this vulnerability is the function fromSetCfm of the file /goform/setcfm of the component httpd. The manipulation of the argument funcname and funcpara1 with an unknown input leads to a buffer overflow vulnerability. And finally in sub_3A5E8 function, the variable of a1 is passed to sprintf, which may overflow the stack-based buffer s.

Source https://github.com/Litengzheng/vul_db/blob/main/FH451/vul_61/README.md

User LtzHuster (UID 95786)

Submission 02/22/2026 06:25 AM (1 month ago)

Moderation 03/06/2026 10:22 PM (13 days later)

Status Accepted

VulDB entry 349579 [Tenda FH451 1.0.0.9 /goform/setcfm fromSetCfm funcname/funcpara1 stack-based overflow]

Points 20

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)