



Home > Submit > 769023

Submit #769023: Tenda FH1202 V1.2.0.14(408) Buffer Overflow

Title	Tenda FH1202 V1.2.0.14(408) Buffer Overflow
Description	Stack-based buffer overflow in httpd: /goform/webtypelibrary invokes formWebTypeLibrary, which concatenates webSiteId into a fixed-size stack buffer using strcat without bounds checks. A long webSiteId overflows the stack, causing DoS and potential code execution.
Source	https://github.com/Svigo-0/Tenda_yul/tree/main/tenda-fh1202-webtypelibrary-webSiteId-buffer-overflow
User	Manner814 (UID: 95971)
Submission	02/27/2026 10:16 AM (1 month ago)
Moderation	03/08/2026 05:23 PM (9 days later)
Status	Verified
VulDB entry	VulDB Entry [Tenda FH1202 1.2.0.14(408) /goform/webtypelibrary formWebTypeLibrary webSiteId stack-based overflow]
Points	17

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)