



Home > Submit > 769178

Submit #769178: Tenda W3 V1.0.0.3(2204) Buffer Overflow

Title	Tenda W3 V1.0.0.3(2204) Buffer Overflow
Description	A stack-based buffer overflow exists in Tenda w3 V1.0.0.3(2204) within formWifiMacFilterGet on /goform/WifiMacFilterGet. The index POST parameter is copied into a stack buffer with no size check. Sending an overlong index triggers stack corruption and process crash, with potential for code execution. The vulnerable path is entered when the handler parses wl_radio and index.
Source	https://github.com/Svigo-0/Tenda_vul/tree/main/tenda-w3-formWifiMacFilterGet-index-buffer-overflow
User	Svigo_0 (UID 95970)
Submission	02/27/2026 03:08 PM (1 month ago)
Moderation	03/11/2026 03:02 PM (12 days later)
Status	Accepted
VulDB entry	[Tenda W3 1.0.0.3(2204) POST Parameter /goform/WifiMacFilterGet formWifiMacFilterGet wl_radio stack-based overflow]
Points	20

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)