



Home > Submit > 769180

Submit #769180: Tenda W3 V1.0.0.3(2204) Buffer Overflow

Title Tenda W3 V1.0.0.3(2204) Buffer Overflow

Description A stack-based buffer overflow exists in Tenda w3 V1.0.0.3(2204) in formWifiMacFilterSet at /goform/WifiMacFilterSet. The GO POST parameter is copied into a stack buffer without bounds checking. A crafted request with a long GO value overwrites stack memory, leading to a crash and potential code execution.

Source https://github.com/Svigo-o/Tenda_yul/tree/main/tenda-w3-formWifiMacFilterSet-go-buffer-overflow

User Svigo_o (UID 95970)

Submission 02/27/2026 03:09 PM (1 month ago)

Moderation 03/11/2026 07:56 PM (12 days later)

Status Pending

VulDB entry 22043 [Tenda W3 1.0.0.3(2204) POST Parameter /goform/WifiMacFilterSet formWifiMacFilterSet index/GO stack-based overflow]

Points 0

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)