





Home > Submit > 769183

Submit #769183: Tenda W3 V1.0.0.3(2204) Buffer Overflow

Title	Tenda W3 V1.0.0.3(2204) Buffer Overflow
Description	A stack-based buffer overflow exists in Tenda w3 V1.0.0.3(2204) in formwriSSIDset at /goform/wifiSSIDset. The GO POST parameter is copied into a stack buffer without length validation. A long GO value overwrites stack memory, resulting in a crash and potential code execution.
Source	 https://github.com/Svigo-o/Tenda_yul/tree/main/tenda-w3-formwriSSIDset-go-buffer-overflow
User	 Svigo_o (UID 95970)
Submission	02/27/2026 03:11 PM (1 month ago)
Moderation	03/11/2026 07:58 PM (12 days later)
Status	Rejected
VulDB entry	22043 [Tenda W3 1.0.0.3(2204) POST Parameter /goform/wifiSSIDset index/GO stack-based overflow]
Points	0

Community Content

Submissions are made by [VulDB community users](#). VulDB is *not responsible* for their content nor the links to external sources.

Please use the raw information shown and the links listed *with caution*. They might contain malicious and harmful actions, code or data.

The corresponding VulDB entries contain the moderated, verified, and normalized information provided within the raw submission.

Documentation

- [Submission Policy](#)
- [Data Processing](#)
- [CVE Handling](#)