



# Download for Tapo C520WS V2

Please choose hardware version:

V2



**Outdoor Pan/Tilt Security Wi-Fi Camera**  
Tapo C520WS

> How to Find the Hardware Version on Your TP-Link Device

**IMPORTANT:** Model and hardware version availability varies by region. Please refer to your TP-Link regional website to determine product availability.

Vx.0=Vx.6/Vx.8/Vx.9(eg:V1.0=V1.6/V1.8/V1.9)

Vx.x0=Vx.x6/Vx.x8/Vx.x9 (eg:V1.20=V1.26/V1.28/V1.29)

Vx.x

Pro

Tapo

Ma

Tapo

Tapo

Set

Tapo App User Guide (for Tapo Indoor Outdoor Cameras) [↓](#)

Tapo C520WS\_V2\_User Guide [↓](#)

Tapo C520WS\_V2\_Quick Installation Guide [↓](#)

Tapo Camera\_Quick Installation Guide(EU1\_12 Languages) [↓](#)

Tapo Camera\_Quick Installation Guide(29 Languages) [↓](#)

✕

## From United States?

Get products, events and services for your region.

GO

Other Option

Setup Video

FAQ

Firmware Release Note

Apps

GPL Code

# Firmware Release Note

Refer the FAQ to update firmware.

## Tapo C520WS(EU)\_V2\_1.2.4 Build 260326

Published Date: 2026-03-27

Modifications and Bug Fixes:  
Enhanced device stability and security.

## Tapo C520WS(EU)\_V2\_1.2.3 Build 251114

Published Date: 2026-01-21

Modifications and Bug Fixes:  
1. Optimized the audio performance.  
2. Enhanced device stability and security.

### From United States?

Get products, events and services for your region.

GO

Other Option

Published Date: 2025-06-03

Modifications and Bug Fixes:

1. Added support for saving recordings to Tapo Hub on the same local network through Device Settings -> Storage & Recording -> Local Storage -> Storage Location.
2. Added support for switching to the optimal network between home Wi-Fi and the Hub's hotspot through Device Settings -> Network Connection -> Wi-Fi Backup.
3. Added support for 12-hour Time option and more timestamp formats.
4. Enhanced device stability and security.
5. Fixed some minor bugs.

## Tapo C520WS(EU)\_V2\_1.0.3 Build 241011

Published Date: 2024-11-25

Modifications and Bug Fixes:  
1. Added support for Adjust Event Type, allows you to manually adjust event types in playback to improve

- the accuracy of detection.
- 2. Added support to fix a static IP address for the camera under Advanced Settings > Network Settings.
- 3. Fixed the issue that the camera would not rotate to the original position after Auto Tracking ended in some scenes.
- 4. Optimized the detection function.
- 5. Improved device stability.
- 6. Fixed some minor bugs.

Sign Up for News & Offers ⓘ

Follow Us

Email Address

Sign Up



About

About

Corp

Our

Sust

Priv

Ethi

Acc

Contact Us

### From United States?

Get products, events and services for your region.

GO

Other Option



©2026 TP-Link Systems Inc. and its affiliated companies. All rights reserved.

Worldwide / English

TP-Link, Tapo, Kasa, Omada, VIGI, Aginet, HomeShield, and Tapo Care branded products are products of TP-Link Systems Inc. or its affiliates.

Note: Some services and materials may require you to accept additional terms and conditions before access or use.

References to "TP-Link" may include TP-Link Systems Inc., its subsidiaries, or business units within the TP-Link corporate structure, as applicable.

The materials provided, including but not limited to press releases, presentations, blog posts, and webcasts, are current as of the date of publication and may be superseded by subsequent updates.