




Notice on Vulnerabilities in FUJIFILM Multifunction Devices and Printers

Vulnerability Description

① Possibility of device hang (CVE-2017-9765)



- ② Possibility of Mass Message Transmission Between Devices (CVE-2024-2169)

- ③ Possibility of device configuration information being read (CVE-2024-51977)

- ④ Possibility of device hang-up (CVE-2024-51979)

- ⑤ Possibility of port scanning (CVE-2024-51980)

- ⑥ Possibility of server-side request forgery attacks (CVE-2024-51981)

- ⑦ Possibility of device reboot (CVE-2024-51982)

- ⑧ Possibility of device reboot (CVE-2024-51983)

Countermeasure

Workaround

-
-

Related Information



Contact

A rectangular input field with a thin black border and a small right-pointing chevron (>) at the end, likely serving as a search or filter bar.